

As indicated in the SACE Environmental and Social Due Diligence Guideline, this is the ex-post disclosure of category A and B transactions guaranteed by SACE in the relevant reporting period. For further information on a specific transaction, please write to contatto.ambiente@sace.it

Project description	Category	Location	Amount <sup>1</sup> (mln EUR)	Environmental and Social standards applied	Environmental and Social information reviewed <sup>23</sup>
Project: Liwa				IFC Performance Standards: 1,2,3,4,5,6,8	
Construction of a new petrochemical complex, pipeline for hydrocarbons transport and wells for gas extraction	А	Sohar – Oman	840 USD	IFC EHS Guidelines: General, Onshore Oil and Gas Development, Large Volume Large Volume Petroleum-based Organic Chemical Manufacturing, Petroleum-based Polymers Manufacturing	ESIA, site visit, further supporting information
Project: Baltic Ammonia Construction of an ammonia production plant	А	Kingisepp - Russia	557	IFC Performance Standards: 1,2,3,4,5,6,8 IFC EHS Guidelines: General, Large Volume Inorganic Compounds Manufacturing and Coal Tar Distillation, Nitrogenous Fertilizer Manufacturing	
Project: Bacia de Santos Etapa 2 Goods and services destined to various oil platforms	А	Santos Basin – Brasil	300 USD	WB Safeguard Policies: Op 4.01, Op. 4.04 IFC EHS Guidelines: General, Offshore Oil and Gas Development	ESIA, and further supporting information

 <sup>&</sup>lt;sup>1</sup> Indicative amounts. Different currencies will be specified.
<sup>2</sup> ESIA stands for Environmental and Social Impact Assessment, ESRQ stands for Environmental and Social Review Questionnaire.

<sup>&</sup>lt;sup>3</sup> Supporting information may include specific environmental and social management plans (e.g. oil spill response plans, waste management plan, etc.), feasibility studies, report prepared by specialized consultants, etc.



Project description	Category	Location	Amount <sup>1</sup> (mln EUR)	Environmental and Social standards applied	Environmental and Social information reviewed <sup>23</sup>
Project: Itare Dam Construction of a dam, reservoirs and pipelines for water supply distribution	А	Rift Valley Region, Kenya	270	IFC Performance Standards: 1,2,3,4,5,6,8 IFC EHS Guidelines: General, Water and Sanitation, Construction Materials Extraction	ESIA, site visit, and further supporting information
Project: Burullus Construction of a combined cycle Power Plant of 4800 MWe	A	Burullus Lagoon, Kafr esh-Sheikh Governorate - Egypt.	217.75	IFC Performance Standards: 1,2,3,4,5,6,8 IFC EHS Guidelines: General, Thermal Power Plants	ESIA, and further supporting information
Project: New Capital Construction of a combined cycle Power Plant of 4800 MWe	A	Cairo - Egypt	217.75	IFC Performance Standards: 1,2,3,4,5,6, 8 IFC EHS Guidelines: General, Thermal Power Plants	ESIA, and further supporting information
Project: Etlik Construction of an integrated health campus	А	Ankara – Turkey	125	IFC Performance Standards: 1,2,3,4,5 IFC EHS Guidelines: General, Health Care Facilities, Thermal Power Plants	ESIA, site visit, and further supporting information
Project: Grati Upgrade of an existing gas fired combined cycle power plant	А	Pasuruan - Indonesia	40 USD	IFC Performance Standards: 1,2,3,4,6 IFC EHS Guidelines: General, Thermal Power Plants	ESIA, site visit, further supporting information



Project description	Category	Location	Amount <sup>1</sup> (mln EUR)	Environmental and Social standards applied	Environmental and Social information reviewed <sup>23</sup>
Project: Eti Bakir Construction of a potassium-based fertilizer plant	А	Kocakent - Mardin Province- Turkey	< 20	IFC Performance Standards: 1,2,3,4 IFC EHS Guidelines: General, Large Volume Inorganic Compounds Manufacturing and Coal Tar Distillation, Base Metal Smelting and Refining, Mining, Phosphate Fertilizer Manufacturing.	ESIA, and further supporting information
Project: NSN Installation of a submarine electric cable	В	United Kingdom and Norway	504 USD	IFC Performance Standards: 1,2,3,4, 6, 8 IFC EHS Guidelines: General, Electric Power Transmission and Distribution	ESIA and further supporting information
Project: HAPI Combined cycle conversion of two existing gas power plants operating at simple cycle	В	Assiut and Damietta - Egypt	400 USD	IFC Performance Standards: 1,2,3,4,6 IFC EHS Guidelines: General, Thermal Power Plants	ESIA and further supporting information
Project: Douala Stadium Development of a soccer stadium and related sporting infrastructures	В	Olembè – Camerun	170	IFC Performance Standards: 1,2,3,4 IFC EHS Guidelines: General, Tourism and Hospitality Development	ESRQ and further supporting information
Project: EGP Solar panels to be installed at 4 different locations	В	South Africa	145	WB Safeguard Policies: Op 4.01, Op. 4.04 IFC EHS Guidelines: General.	ESIA and further supporting information



Project description	Category	Location	Amount <sup>1</sup> (mln EUR)	Environmental and Social standards applied	Environmental and Social information reviewed <sup>23</sup>
Project: Sibur Upgrade of an existing petrochemical plant	В	Tomskneftekhim – Russia	74	WB Safeguard Policies: Op 4.01 IFC EHS Guidelines: General, Petroleum Based Polymer Manufacturing.	ESRQ and further supporting information
Project: Suriname University Construction of dormitories, auditorium and researches labs within the existing university campus	В	Paramaribo – Suriname	24	WB Safeguard Policies: Op 4.01 IFC EHS Guidelines: General.	ESRQ and further supporting information
Project: Peker-Belenco Quarts slabs processing line to be installed in a manufacturing existing plant.	В	Manisa – Turkey	< 20	WB Safeguard Policies: Op 4.01 IFC EHS Guidelines: General	ESRQ and further supporting information
Project: Mozyr (II phase) Hydrogen production plant to be built within an existing refinery	В	Mozyr – Belarus	< 20	IFC Performance Standards: 1,2,3,4 IFC EHS Guidelines: General, Petroleum refining	ESRQ and further supporting information